




a xylem brand




VIS/CT

Cleaning the measuring window:




Soak flocked cleaning card with cleaning agent.

Cleaning the measuring gap:



Cut stripes from cleaning card:

Measuring gap 1 mm:



Measuring gap 5 mm:

